


HORIZONTAL  
STRESS CRACKING



## SECTION OF HULL/DECK JOINT H-376