

Patching of hole on Actex-1 hull

- ① Original hole 2-3mm ϕ
- ② Drill bigger 3-4mm ϕ
- ③ Countersunk both ends of hole
- ④ Stuff hole with 2-part Epoxy.
- ⑤ Gap between Battery table & hull is hard to reach. Hence to need to stuff epoxy from top & bottom.

