



FF2 HALYARD TOP FITTING UPDATE

This document provides information regarding an update to the Installation/Operating Instructions that was shipped with your furler.

Please make the following change on Page 5:

Cut the top end of the luff extrusion to 13” less than pin-to-pin length.



FF2 HALYARD TOP FITTING UPDATE

