

Important information concerning forestay fitting 517-914 (2004 – 2008)

Dear Sir/Madame,

It has been brought to our attention that a few forestay fittings of this design have failed due to a crack in the welding. The crack develops along the weld on the rear side of the fitting inside the mast. It is not visible from the outside. The suspect production batches were used during the period 2004-2008.




All the failed fittings origin from long distance cruising boats with inadequate rig tune and long periods of sailing using only the genoa.

Only masts exposed to forestay loads exceeding a critical limit are at risk and we have listed all of these boats, see below.

We kindly ask you for your cooperation and suggest the following action plan to be completed before the boat is sailed again:

1. Check, before further sailing is done, if your boat is on the list below. If so, please verify that your mast has a forestay fitting marked with the article number 517-914. The number is stamped in the stainless plate and is easy to check from the outside.
2. If that is the case, please fill out and send the [digital form](#) for contacting Seldén.
3. Seldén will immediately deliver a replacement fitting, art no 517-914-90.
4. When the exchange is completed, please would you leave the original fitting with the nearest Seldén Service centre. They are all listed on our website. Please mark the fitting with your name and the ID number of your boat. The ID number is engraved in to the stern of the hull and has the format (example):



If the boat is no longer in your possession, we kindly ask you to inform us the name and contact details of the new owner.

Seldén's commitment is limited to providing a new fitting with instructions, and being available for consultation by phone or email during the exchange of the fitting. We do not compensate lost usage or lost revenues from charter operations or any other costs relating to this recall.

Contact details:

www.seldenmast.se
Seldén Mast AB
Box 14
S-421 21 V. Frölunda
Telefon: +46 (0)31 696900
Fax: +46 (0)31 297137
E-mail: 914@seldenmast.se

PLEASE NOTE!

Forestay fittings marked with article number 517-924, used 2007 and onwards, are not affected by this recall.



We regret this unfortunate situation but would like to stress the importance of immediate action in order to guarantee safe and pleasant sailing.

Best regards,
Seldén Mast AB

Peter Rönnbäck
CEO

The following boats are affected, model years 2004-2008			
Arcona 460	Najad 460	Sweden Yacht 45	Etap 46 DS
Bavaria 46	Najad 400	Comet Pheonix 50	Falcon 44
Dehler 47 Rod	Najad 405	Incistor	Van de Stadt 44 Phaff
Elan Impression 434	Najad 440	NIC 45	Van de Stadt 44 Pol
Elan Impression 444	Omega 46	Reflex 38 Option 2	Hunter 426
Finngulf 44 19/20	Pronavia 42 Sport	Southerly 42RS	Hunter 49
Hallberg Rassy 40	Salona 45	Van de Stadt 44	Saga 409
Maxi 1300	Sweden Yacht 42	Brouwer 45 Conv	

Seldén Mast AB **ADDRESS** Box 14, SE-421 21 Västra
TELEPHONE +46 (0)31 69 69 00 **FAX** +46 (0)31 29 71 37
E-MAIL info@seldenmast.com **INTERNET** www.seldenmast.com
PLUSGIRO 62 05 62-9 **BANKGIRO** 441-7630

ORGANISATION NO 556113-6945 **VAT REG.NO**
BANK Nordea Bank AB **ACCOUNT NO** 3053 7702520
SWIFT NDEASESS **IBAN** SE25 3000 0000 0305 3770
Innehar F-skattsedel