



Sole before cutting




Cutting skin off sole



Digging Out delaminated plywood



Actual core piece-delaminated



Sole glass center



Using old sole cutout
as template to place holes.

Note that old sole has no cracks despite having
a completeley delaminated core.

