



Suggested way
to repair if embedded
metal plate thread
is stripped.

- ① Drop string through hole
- ② secure string to small \varnothing bolt (in saloon)
- ③ Pull string & bolt up to deck (stanchion)
- ④ Carefully put nut on bolt & secure stanchion.
- ⑤ can saw a excess bolt tip or put plastic cap on it.

(This area no access)